## MEETING MEMORANDUM

TO:

FILE

FROM:

TOM OVERTURF /

DATE:

**AUGUST 23. 1996** 

SUBJECT: MCLAREN HART MEETING

## Attending:

Hassan Amini, Tabb Bubier, Richard Richter and Michael Dzubnar from McLaren Hart Scott Lattimore from DAC

Mario Stavale and Tom Overturf from MDRC

- Biggest problem on our site is tank spill between Buildings 1 and 36 (per Kennedy 1. Jenk's report):
  - Toluene at <u>6,300</u> mg/kg at 20' (10'-85' range) Α.
  - 1,1,1 TCA at 59,000 mg/kg at 60' (15'-65' range)
- Also have problem at Lockheed Martin property line (3,000 mg/kg TCE (west side 2. of our site - sure looks like it's from Lockheed Martin!!!) also some toluene.
- Montrose well data (south end of our site) has 830 mg/kg benzine and toluene. 3.
- Shallow (Bellflower) groundwater (65' flows at 100' per year northwest to 4. southeast) is totally impacted regionally so no reason to require one site to try to cleanup. It's perched or semi-perched on tight clay so it's really an "aquitard" that protects drinking water at Silverado Aquifer at 390'-450' below grade and potentially Gage Aquifier at 100' (which we can argue isn't a drinking water aquifer anyway).
- Pump and treat is no longer recognized as a reasonable remediation alternative 5. either by jurisdictional agencies, consultants or owners. Agencies now recognize financial feasibility in remediation. Greatly relaxed requirements over last 2-3 years particularly. Contaminated property owner is now "client" so regulatory attitude is much improved.
- 6. Abbreviations:
  - A. MCL Maximum Contaminated Lead which is "drinking water standard".
  - LLNL Lawrence Livermore National Lab (Study). B.
  - EF&T Environmental Fate and Transport (Models). C.
  - Brownfields Clinton Administration bill to incentivize cleanup for development.

McLaren Hart Meeting Memo August 23, 1996 Page Two of Two

- 7. Chinese Wall None of McLaren Hart people assigned to this project have or will work on Montrose site or have any contact with those staff people. They will make public studies available (increases efficiency). Not very convincing however!!
- 8. Montrose site has totally different chemicals, depths, problems readily separable and identifiable.
  - A. DDT near surface soils problem airborne.
  - B. Dichlorobenzine used in manufacturer of DDT by Montrose.
- 9. McLaren Hart has done similar joint MDC/Lockheed Martin site remediation at Stringfellow Superfund Site (last page of reference section).
- 10. Comments on presentation (inferior to Montgomery Watson):
  - A. New personnel from earlier presentation new guys were not familiar with MDRC objectives or site.
  - B. Presentation slow, not focused. Graphics, plans, and tabulation on screen, but not in handout.
  - C. Poor response to potential for conflict and opportunity to list advantages of this work.

**TAO:kk KKT01807** 

cc: Mario Stavale
Tom Motherway
Phil Cyburt
Steve Barker
Merle Pautsch